

Page 1

Wednesday, May 19, 2010 10:43:23:AM Item ID: D3564-3 Accept Setup Start **Revision ID:** Wearshoe Stop Item Name: 5/19/2010 **Start Qty: 12.00 Start Date: Cust Item ID: Required Date: 5/26/2010** Req'd Qty: 12.00 **Customer:** Reference: Run Start Date/15-1 Process Plan: Tooling: Approvals: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Draw Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Number Rev. Code Qty Qty Number Stamp Draw Nbr **Revision Nbr** D3564 Rev D. 100 0.00 FLOW WATER JET B10-8-25 Waterjet 0.00 Memo 1-Cut as per Dwg D3564 \*\*\*\*\*(D3564-1F)\*\*\*\*\* Dwg Rev: FLOW CNC Waterjet 304.063 Rev: \( \bigcap \) \( \text{\$\pi\$} \) \( \text{\$\pi\$} \) \( \text{\$\pi\$} \) 110 QC2- Inspect parts off machine FAI/FAIB 0.00 B10-S-28 0.00 Memo Quality Control 120 QC8- Inspect parts - second check 2 wlater Memo **Quality Control** 

Dart Aerospace	Ltd
----------------	-----

W/O:	WOTH OTDER OTARGES											
DATE	STEP	PRO	CEDURE CH	HANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								<del></del>				
Part No: PAR #: F			Fault Ca	tegory:		_ NCI	R: Yes I	No <b>DQ</b>	A:	_ Date: _		
Part No: PAR #: Fault Category:  Resolution: Disposition:  NCR: WORK ORDER NON-CONFOR					QA:	N/C Clo	sed:	<del></del>	Date:			
NCR:		V	WORK OR	DER NON	-CONFORM	ANCE	(NCR	)				
DATE	STEP	Description of NC	Initial	Correctiv		ction B	Sian 2		cation	Approval Approva		
		Section A	Chief Eng	ACU	on Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector	
				-								
											i i	
				79								
						· .						
NOTE	ato & initio	I all entries								i		
	are a milla	i ali cillico										

#### Work Order ID 58825

Wednesday, May 19, 2010 10:43:23 AM



Page 2

Item ID:

D3564-3

Accept

Setup Start



**Revision ID:** 

**Start Date:** 

Item Name: Wearshoe

**Required Date: 5/26/2010** 

5/19/2010

**Start Oty: 12.00** 

Req'd Qty: 12.00



Date: \_\_\_\_\_

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan: Date: Tooling:

SPC (Y/N):

0.00

0.00

Date:

Run

Stop

Start

Stop



Sequence ID/

Work Center ID

130

Brake NC

Operation **Description** 

NC BRAKE

Set Up/

**Run Hours** 

Draw Number

Draw Rev.

Date:

Plan Accept Qty Code

Reject **Qty** 

Reject Insp. Number Stamp

Brake NC

Deburr if necessary ☐ Form on Brake as per Dwg D3564 using Jigs DT8179 and DT8155 ☐ Form Joggle as per Dwg D3564 on brake using Jig DT8157

Sp lobslace

140

QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

0.00

0.00

150

Large Fab Large Fab

Large Fab

Memo

Ensure joggle as per dwg D3429

Batch □ A/R

2059B Hardcoat



Description

Memo

□Weld hardcoat as per Dwg D3437

M114642

Dart	Aer	os	pace	Ltd
------	-----	----	------	-----

W/O:			W	ORK ORDER CHAN	GES	***************************************				
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					•				•	
									·	
Part No	:	PAR #:	Fault Cate	egory:	NCI	R: Yes 1	No DQA	\:	_ Date: _	
Resolution: Disposition: (					QA	N/C Clo	sed:			
NCR:			WORK ORD	ER NON-CONFORM	IANCE	(NCR)				
DATE	STEP	Description of NC	Initial		ction B	Ciam 0	Verific		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
		<i>,</i> •					i			
				,				i		
				74						

#### Work Order ID 58825

Wednesday, May 19, 2010 10:43:23 AM



Page 3

Item ID:

D3564-3

Accept



Setup Start

Stop



**Revision ID:** 

Item Name:

**Required Date: 5/26/2010** 

Wearshoe

5/19/2010

**Start Oty: 12.00** 

Req'd Qty: 12.00



**Cust Item ID: Customer:** 

Reference:

**Start Date:** 

**Approvals:** 

Process Plan: \_\_\_\_ Date:

Tooling:

Date:

Run Start



QC: \_\_\_\_\_ Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID

160

QC

Quality Control

Operation Description

QC10- Inspect visual per QSI004- ground welds

Set Up/ **Run Hours** 

Draw

Draw Number Rev.

Plan Code

Reject Accept Qty

Reject Insp. Number Stamp

Memo

0.00

170

QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

Qty

180 Powdercoat

Powder Coating

Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

M112588

0.00 => H coloclio

Memo

Memo

START\_TIME: [2] FINISH TIME:

0.00

\_OOVEN TEMPERATURE:

X12 9 \_\_\_\_

	-		•							,
W/O:			V	VORK ORDER CHAN	IGES				····	
DATE	STEP	PROC	EDURE C			By Date Qty Appro Chief Er				Approval QC Inspector
					-					
			·····					-		
							-			
· · · · · · · · · · · · · · · · · · ·	<u> </u>								•	
Part No		PAR #:		A. C.						
	R	esolution:	_ Disposit	tion:	QA	: N/C Clos	sed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORI	MANCE	(NCR)				
DATE	STEP	Description of NC			Section B		Verifica	ation	Approval	Approval
	J	Section A	Initial Chief Eng	Action Descriptio Chief Eng	<b>n</b> 14	Sign & Date	Sectio	Section C	Chief Eng	Approval QC Inspector
										·
									-, ,	
		·								
				•					·	
	-									

### Work Order ID 58825

Wednesday, May 19, 2010 10:43:23 AM



Page 4

Item ID:

D3564-3

Accept

Setup Start

Stop



**Revision ID:** 

**Start Date:** 

Item Name: Wearshoe

Required Date: 5/26/2010

5/19/2010

**Start Oty: 12.00** Req'd Qty: 12.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

OC:

Date:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Stop

Sequence ID/ Work Center ID

190

Quality Control

Operation Description

QC3- Inspect Part Finish

0.00

Draw Number

Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Insp. Number Stamp

200

Packaging

Packaging

Memo

Memo

Memo

0.00

0.00

210

QC

Quality Control

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

0.00

W/O:			V	VORK ORDER CH	ANGES			<del></del> -		4
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Osed:	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
٠										
Part No: PAR #: Fault Category			tegory:	NC	R: Yes	No <b>DQ</b>	A:	Date:		
Resolution:		esolution:								
NCR:			WORK OR	DER NON-CONF	ORMANCE	(NCR	)			
DATE	STED	Description of NC		<b>Corrective Action</b>	Section B		Verific	cation	Approval	Approval
DATE	DATE STED Description of NC	Initial Chief Eng	Action Descri Chief Eng	ption	Sign & Date	Secti	on C	Chief Eng	QC Inspector	
				,					:	
		,	:							
						.,				W <sup>1</sup> -1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
									i	
		,								
								<del></del> -		
								į		

#### **Picklist Print**

Wednesday, May 19, 2010 10:43:27 AM

Work Order ID: 58825

Parent Item:

D3564-3

**Parent Item Name:** 

Wearshoe

Comments: IPP Rev:A

IPP Rev:B

New Issue 07-03-08 ec

As per Rev C 07-07-09 JLM

IPP Rev:C

As per Rev D 07-09-09 JLM Verified By:EC

**Start Date:** 5/19/2010

Required Date: 5/26/2010

**Start Qty: 12.00** 

Required Qty: 12.00

Component Item ID/ M304S16GA

Replacement Mfg/ Purchased

Bin No

**Primary** Last

Route

100

Unit of sf

Qty on 65.3548

Qty per Kit 1.1

Qty L3,

Status

Page 1

1B10-5-85

Date

304/316 Sheet .063

Location MAT

111323 114467

Loc Qty 65.3548 65.3548 Loc Code

114467



W/O:			WC	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #			Fault Cate	jory:	NCR: \	res N	o <b>DQ</b>	A:	_ Date: _	
	Res	olution:	Disposition	n:	QA: N/	C Clos	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	IANCE (N	ICR)				
DATE	STEP Description of	Description of NC	f NC Corrective Action Section B			- Verificat			Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Date	Secti	on C	Chief Eng	QC Inspector
			;							

DART AEROSPACE LTD	Work Order:	58825
Description: Wearshoe	Part Number:	D3564-3
Inspection Dwg: D3564 Rev: D		Page 1 of 1

### FIRST ARTICLE INSPECTION CHECKLIST


X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	+/-0.010	7.007			·	
2.432	+/-0.010	2,437	>0			
2.50	+/-0.030	7.50	6			
6.000	+/-0.010	60.0	A			
12.104	+/-0.010	12.164	×			
18.000	+/-0.010	18.000	*			
18.000	+/-0.010	18.000	O			
18.00	+/-0.030	18.00	8			
9.00	+/-0.030	9.00	2			
11.50	+/-0.030	11.50	٧	***		
0.300 x 0.300	+/-0.010	1302×304	8			
Ø0.188	+0.005/-0.001	-i92	×			
R0.375	+/-0.010	,375	۵			
0.063	+/-0.010	820.	>			
				*		
·						
						,


Measured by:	B	Audited by:	8	Prototype Approval:	N/A
Date:	10-2-05	Date:	1805/25	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.09.06	New Issue	KJ/JLM .	
В	08.09.04	Dwg Rev updated	KJ/DD ox	13/
				<del></del>

W/O:	<del></del> _		WC	RK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
		4								
							,		·	
			٠ .							
Part No	:	PAR #:	Fault Cate	gory:	_ NCR:	Yes 1	No DQA	<b>\</b> :	Date:	
		esolution:								
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (	(NCR)	)			
DATE	STEP	Description of NC	) — — — — — — — — — — — — — — — — — — —	Corrective Action Section			Verific	ation	Approval	Approval
DAIL	) Î	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
•			,							
				٠.						
					ţ					




W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP PROCEDURE CHA			ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1 rod wigi	
	<u> </u>								
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Yes	No <b>DQ</b>	<b>A</b> :	_ Date: _	
		esolution:							
NCR:			WORK ORI	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC			ction B	Verifi	cation	Approval	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	&   Sect	ion C	Chief Eng	QC Inspector
						į			
	·								
			1		i	1			



Dart Aerospace Lte	d
--------------------	---

W/O:			W	ORK ORDER CHA	ANGES					
DATE STEP		PR	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
Part No		PAR #:	Fault Cate	egory:	NC	R: Yes	No <b>DQ</b>	A:	Date:	
	Res	olution:	Disposition	on:	QA	: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFO	RMANCI	E (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section			Ciara 0	Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign & Date	Secti	on C	Chief Eng	QC Inspector
								!		
<u>-</u>										



Dart Aerospace Ltd	Dar	t Ae	rost	oace	Ltd
--------------------	-----	------	------	------	-----

W/O:			WO	RK ORDER CHAI	MCES			·		
DATE	STEP	PRO	OCEDURE CHAI		NGES B	y	Date	Approval Chief Eng /	Appioval	
		-							Prod Mgr	QC Inspector
									· · · · · · · · · · · · · · · · · · ·	
	ļ									
	W									
- <del></del>						li.				
Part No:		PAR #:	Fault Cate	jory: LS	NCR: `	∕es_N	o DQA:			
	R	esolution:	Disposition	1:	QA: N/	QA: N/C Closed:				
NCR:			WORK ORDE	R NON-CONFOR	MANCE (N	(NCR)				
DATE	ne De	Description of NC	Corrective Action Section				Varification	tion	Ammuoval	Approval
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	on S	ign & Date	Verification Section C		Approval Chief Eng	QC Inspector
							_			
									i	
								,		
					ļ					
									:	
										•